

2110Z 28 DEC 64

TOP SECRET

TO : DIRECTOR

FROM : [REDACTED] 25X1A

SUBJECT:

INFO :

PRIORITY

TOR 0331Z 29 DEC 64

25X1A

25X1A

OPS 1-10

IN 64698

TO

PRIORITY [REDACTED]

INFO PRIORITY [REDACTED]

CITE

68

25X1A

25X1A

A. T344A

B. GOOD

C. THE METERING IS IRREGULAR, RANGING FROM A MAXIMUM IN EXCESS OF ONE INCH TO A MINIMUM OF LESS THAN ONE TENTH INCH. A NUMBER OF FRAMES ARE BUTTED TOGETHER AND OTHERS ARE OVERLAPPED APPROXIMATELY FIVE PERCENT. THE OVERLAPPING FRAMES OCCUR MORE FREQUENTLY ON THE 9L SIDE.

END OF MSG

TOP SECRET

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING

DATE 2100Z 28 DEC 64

TOP SECRET

2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO : DIRECTOR

FROM : [REDACTED] 25X1A

ACTION:

INFO:

PRIORITY

FOR: 0328Z 29 DEC 64

25X1A

25X1A

IN 64696

TO PRIORITY [REDACTED]

INFO [REDACTED]

ONE [REDACTED]

0567

25X1A

A. T344A 25X1A

B. 119/B/6335 [REDACTED]

C. BOTH 9L AND 9R PROCESSED ON TRONTON NBR 2. TEMP IN DEGREES F. PRIMARY 70. SECONDARY 80. DEV. AS FOLLOWS, IN FEET, SAME 9L AND 9R

0000-0120 MAX.

0121-0908 INTERMEDIATE

0909-0990 MAX.

0991- TAIL INTERMEDIATE

D. GAMMA 9L, J START 2.58, FINISH 2.68

9R, START 2.66, FINISH 2.61

E. 9L, 9J-46-4000, 44-17-6-4

9R, 9J-46-4000, 32-28-30-5-4

F. QUALITY EVALUATION

1. RECEIVED DRY IN METAL BOXES

TOP SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING
AND DECLASSIFICATION

25X1A

T O P S E C R E T

██████████ 0567 (IN 64696) PAGE TWO

2. GOOD
3. GOOD
4. GOOD
5. GOOD
6. IRREGULAR, SEE REMARKS
7. OVEREXPOSED BUT READABLE

G. THE METERING IS IRREGULAR AND RANGES FROM MORE THAN ONE INCH TO LESS THAN ONE TENTH INCH. IN ADDITION, SOME FRAMES ARE BUTTED TOGETHER AND OTHERS OVERLAP APPROXIMATELY FIVE PERCENT. THE OVERLAPPING OCCURS MORE FREQUENTLY ON THE 9L SIDE. BOTH FILM EDGES CONTAIN MINOR STATIC DISCHARGES. ROLLER INDUCED STATIC DISCHARGES (ROLLER CHATTER) ARE MINOR AND FEW.

H. HELD AT ██████████ FOR REPRODUCTION.

28 DECEMBER 1964, 1930Z

25X1A END OF MESSAGE

T O P S E C R E T